# Case Study



# Contaminated Soil Removal at Rail Depot

# Client

Hochtief UK Construction Ltd.

#### Remediation Value

£1,500,000

#### Site

34,000m<sup>2</sup> site, adjacent to the river, with a future commercial land use. Historically the site was used as a railway depot and railway goods depot. The surrounding land has been used for industrial and railway related purposes.

#### Contaminants

Heavy oils, hydrocarbons and asbestos.

## **Remediation Methods**

Pre-excavation delineation of contamination hotspots and pre-classification of waste streams.

Hand-picking of asbestos.

Off-site disposal of visible asbestos, hazardous and non-hazardous soils to UKRL's soil treatment facility, and subsequent re-use of treated stone onsite.

Removal of below ground obstructions.

Screening of soils to segregate clean stone to be reused on site as part of the piling mat.

Crushing of concrete to specification for site re-use.

Reduce level dig to design levels; placement of pile mat to level.

Working to geotechnical specification.

# Challenges

- · Working immediately adjacent to live railway.
- Unexpected contamination encountered at depth.
- Deep buried obstructions, not previously surveyed.
- Requirement to remove all abnormals to enable a driven pile foundation solution.
- Segregation of all materials due to chemical and geotechnical properties.

## **Approach**

- Detailed site investigation involving trial pitting using a 10m x 10m grid system to delineate contamination and identify underground obstructions.
- Ex situ bioremediation of hydrocarbon impacted soil at UKRL's soil treatment facility.
- Segregation and hand-picking of visibly asbestos contaminated material to enable site reuse.
- Full excavation of contaminated soils and validation of excavations.
- Excavation of sumps to enable free-product recovery.
- Installation of impermeable membrane to prevent migration of contamination into site from an off-site source.

Screening of soils to segregate stone for re-use



Evidence of free product on groundwater



Hydrocarbon impacted soils awaiting excavation

